IN THE SPECIFICATION:

The specification as amended below with replacement paragraphs shows added text with underlining and deleted text with strikethrough.

Please REPLACE paragraph [0005] on page 2 with the following amended paragraph:

[0005] However, in consumer devices (for example, <u>a</u> home DVD player) capable of reproducing the interactive DVD (i.e., capable of supporting an interactive mode), a problem exists in buffer management for supporting the interactive mode. FIGS. 1a-1A and 4b-1B are reference views for easily explaining a problem in a conventional technique.